

PFAS Workflow for *Solid Samples*

X-TRACTION® PFAS (PFE*)

For Extraction



D-EVA Concentration

For the sensor controlled evaporation of extracts




FREESTYLE™ SPE PFAS

For clean-up up to 50 mL
(e.g. Dual SPE)



EluCLEAN® PFAS

SPE columns



D-EVA Concentration

For the sensor controlled evaporation to a few µL



* Pressurized fluid extraction

PFAS Workflow for *Aqueous Samples*

FREESTYLE™ XANA PFAS


For clean-up of up to 4 L



or

FREESTYLE™ XANA PFAS TableTop

For clean-up of up to 250 mL



+

EluCLEAR® PFAS

SPE columns



D-EVA Concentration

For the sensor controlled evaporation to a few µL

